.™ Nº 10572

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	1
DATE INSPECTED	IF SO HOW AND LÉCATION FROM
,	FIRST MANHOLE DOWN STREAM
HOUSE NO	
	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT
	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	La ser also years
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
	3
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	LL OF BUILDING SERVED.
	}
ā	
ž.	
Mr. To our out	in panal
No Inspect	cion Records
	and the second of the second o
	x
9	
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE
, mapector for city	
REMARKS	



N		
7	$N_{\bar{0}}$	10572
/ }	ſ	THE STATE OF THE S

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

TWO WORKING DAYS  BEFORE YOU DIG	PERMIT TO TAP SEWER
COLL 800-362-2764 TOLL FREE OHIO UTILITIES PROTECTION SERVICE EXON-MEMBERS MUST BE CALLED DIRECTLY	MASSILLON, OHIO, Dept 9, 19 96 Develop ( FEE OF \$ 5000
for which permission is granted	me
TO TAP Sar	sewer on the north sid
OF Shaw aue, NE AVE ST.	SEWER ON THE SID
THE PREMISES BEING LOT NO. 1395	1, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES
OF THE DEPARTMENT OF PUBLIC SERVICE.	no units (1).

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.