Nº 10617

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-11-97	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 1850				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? 455				
, ,	NAME OF CONTRACTOR Bontages Effect			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	13' 10's 41' 10'DEE)			
SIGNED BUO CARRE	FILED AT ENGINEER'S OFFICE			
Inspector for City				

Nº 10617

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHI	0,	3/1
RECEIVED OF	<u>Bartinger</u>	Efe	FEE OF \$50
OR WHICH PERMISSION IS GRANTED	·		
O TAP	SEWER ON THE	<u>la a a</u>	
15			
HE PREMISES BEING LOT NO		1	
VORK TO BE DONE IN ACCORDANCE WIT		PASSED BY THE CIT	ry council, and
IAME OF CONTRACTOR	igu Eflevari	Edg	٠
Note: This permit co	overs work outside of	building only.	Any work

walls of building is subject to Massillon Board of Health Regulations.