Nº 10621

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4.22.97	IF SO HOW AND LOCATION FROM 137			
HOUSE NO	DISTANCE FROM FIRST MANHOLE			
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	- 4 1			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Holder Leaves			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	N A			
10 DEF 1	- CURB			
7	/21' /37' (0 m-1			
SIGNED 3 10 Cannot Inspector for City	FILED AT ENGINEER'S OFFICE			
7/ 110/2000				
REMARKS				

Nº 10621

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILL	ON, OHIO,	3/21
RECEIVED OF	Mexical	Runde	$14a$ FEE OF $5\overline{A}$
OR WHICH PERMISSION IS GRANTED			
epaul de la lang	SEWER ON T	THE ALMOT	<u> </u>
F 5/44th 7/6	AVE.	REET	edilt.
HE PREMISES BEING LOT NO/_		·	
ORK TO BE DONE IN ACCORDANCE W	TH ORDINANCE NO. 19-19		
AME OF CONTRACTOR	the flound	ling.	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.