Nº 10627

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-31-97	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 3536	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YES	<i>→</i> . A ~	
WAS ATTACHED TO MAIN 165	NAME OF CONTRACTOR Tised Effe	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	101 100 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
SIGNED Bille Carry // Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 10627

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,_	March 31	
RECEIVED OF	<u> </u>	FEE OF \$/23	
FOR WHICH PERMISSION IS GRANTED	E<<		
TO TAP	SEWER ON THE	rast.	
of	AVE. ST. TYPE OF STREET	Industrial	
THE PREMISES BEING LOT NO.			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR TIST EXC	~~~~~~~~		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.