## Nº 10647

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-4-97	IF SO HOW AND LOCATION FROM Gores Into MA
HOUSE NO. 2629	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	NAME OF CONTRACTOR Bill Cauce
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
	12 1 1 1 1 N
Bill Presser	224 S OBB
Inspector for City	

## Nº 10647

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, O
RECEIVED OF FEE OF \$ SC
OR WHICH PERMISSION IS GRANTED
O TAPSEWER ON THESEWER ON THE
F- 1-100 2000 My ST. TYPE OF STREET Condend Comme
HE PREMISES BEING LOT NO, HOUSE NO2629
YORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.