

N^o 10649

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-17-97

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

24'

HOUSE NO. 227

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Bill Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Glick
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10649

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 3

RECEIVED OF William L. Clark

FEE OF \$ 52

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary

SEWER ON THE West

OF 25th

NW

AVE.

ST.

TYPE OF STREET

THE PREMISES BEING LOT NO. 13122

, HOUSE NO. 227

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR William L. Clark

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**