

N^o 10672 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-30-97 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 262'
HOUSE NO. 317
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Larry Murphy
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

RED
HEAD
H

Z
K

→ 262' DSM+ + 8' DEEP CURB

SIGNED B. J. P. Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 10672

OFFICE OF THE DIRECTOR OF PUBLIC SEI

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/24

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**