Nº 10674

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-5-97	IF SO HOW AND LOCATION FROM 158
HOUSE NO. 1/18	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 155	
	2/ Palla Russia
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	3'0FF)
	450 -12
	30 8055
SIGNED BULL SIGNED Inspector for City	filed at engineer's office

Nº 10674

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF	-A $-A$	LON, OHIO,	10/ FEE OF \$ 2	
FOR WHICH PERMISSION IS GRANTED	Atheritat			
TO TAP	SEWER ON	THE	<u> </u>	
of <u>A. 2. B. 14. 1</u>			and the second second	_
THE PREMISES BEING LOT NO			<i>i</i>	
WORK TO BE DONE IN ACCORDANCE WITH	E. 1		THE CITY COUNCIL, AND)

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.