Nº 10675

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-5-97	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 775		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 45		
WAS ATTACHED TO MAIN 15	NAME OF CONTRACTOR 26 old alsour	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	9' + 3' p & BP	
	30'	
	43 12'0) 8'D&E	
	45 X 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
SIGNED BELL PASSAL Inspector for City	FILED AT ENGINEER'S OFFICE	

## $N^{\circ}$ 10675

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	
RECEIVED OF	, Naldeska	LIST FEE OF \$ 5.46
FOR WHICH PERMISSION IS GRANTED	Lit	
TO TAP	VER ON THE	en de de la companya
OF AVE. ST. TY.		• •
THE PREMISES BEING LOT NO		<i></i>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	). 19-1971 DULY PASSED E	BY THE CITY COUNCIL, AND I
NAME OF CONTRACTOR	hadangarahan	

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.