## $N^{0}$ 10697

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
	general section of the section of th
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 10697

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	//, MAS	SILI/ON, OHIO,		//3
RECEIVED OF		Valdert		
OR WHICH PERMISSION IS GRANTED				
O TAP Thinkfring	· ·			
or Buy what SE			<i>3</i>	
THE PREMISES BEING LOT NO. DL	461	, HOUSE NO	65	70
YORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE.	RDINANCE NO. 19	-1971 DULY PASSE	D BY THE CITY	COUNCIL, AND
NAME OF CONTRACTOR ALLALA	Gullan.	A		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.