Nº 10699

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1-26-98	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2520	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 1755	NAME OF CONTRACTOR Malawities Exerg
WAS ATTACHED TO MAINS	NAME OF CONTRACTOR // alasmue fees
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	1 12 6 DEBP Nd
Bill Car	22° // DJETE / P
SIGNEDInspector for City	TILED AT ENGINEER O OFFICE
DEMADKS	

Nº 10699

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,L_Z_3
RECEIVED OF	LOCIFICA CONSTRUCTION THE FEE OF \$50.
FOR WHICH PERMISSION IS GRANTED	MALALTE EXCOVATIONS
TO TAP	SEWER ON THE
OF_Taltrom-ClAle	AVE. ST. TYPE OF STREET Property Control
THE PREMISES BEING LOT NO. 15445	7, HOUSE NO. 2520
WORK TO BE DONE IN ACCORDANCE WITH O	ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR WALANTE	EXCAVATING

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.