$N^{\underline{0}}$ 10718

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-24-98	IF SO HOW AND LOCATION FROM LAL GOES INTO MH IN BACK YARD		
HOUSE NO. 2716	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN 1955	NAME OF CONTRACTOR 26 6 Experience		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	153 Lot. 11Ne		
10 (10 10 10 10 10 10 10 10 10 10 10 10 10 10 1	$\uparrow \downarrow \downarrow \downarrow$		
	Curo		
	CURB		
SIGNED Bill Cassas Inspector for City	FILED AT ENGINEER'S OFFICE		
inspector for City			
REMARKSCutoff	·		

Nº 10718

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	/ MASSILLON, O	эню,4//3
RECEIVED OF		FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
TO TAP ON THE STATE OF THE STAT	SEWER ON THE	JA Shook
OF Liversky Klass &	AVE.	and the second
y,		2=11/1-
THE PREMISES BEING LOT NO	, 1	HOUSE NO.
WORK TO BE DONE IN ACCORDANCE WITH ORDI	NANCE NO. 19-1971 DU	ILY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	uti it day	<i>i</i>
NAME OF CONTRACTOR	الا معمالية من شائلة كانت الكاملية عن التي منها الكوار	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.