Nº 10719

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-7-98	IF SO HOW AND LOCATION FROM 86	
HOUSE NO. 1756 - 1756	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR CHill Threeling	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
35 	5/pso/9 curs	
SIGNED Build grand Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

## Nº 10719

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

4.	MASSILLON, OHIO,
RECEIVED OF LONG	4444 FEE OF \$/2
FOR WHICH PERMISSION IS GRANTED	
TO TAPEL SE	EWER ON THE ALTA
OF ALL LOS ST. T	YPE OF STREET 4 A SA A LA
THE PREMISES BEING LOT NO.	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR LA	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.