Nº 10724 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-15-98	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	<u>-</u>	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 155		
WAS ATTACHED TO MAIN 76 5	NAME OF CONTRACTOR Bushage Washington	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	LIDE P	
· · · · · · · · · · · · · · · · · · ·	/36' CURR >	
my		
SIGNED BILD RUDON	7 FILED AT ENGINEER'S OFFICE	
SIGNED Inspector for Cl	ty	
REMARKS		

Nº 10724

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

y MASSILLON, OHIO,	5/12
RECEIVED OF JUCKLES WHICKING	FEE OF \$/5
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON THE	Mest
of 1 th 1 AVE. ST. TYPE OF STREET	asphalt
THE PREMISES BEING LOT NO. 19/1	e no
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY P.	
NAME OF CONTRACTOR AMELIE AMELIE	/
Note: This permit covers work outside of bu	

walls of building is subject to Massillon Board of Health Regulations.