## $N^{\underline{0}}$ 10753

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-22.98 HOUSE NO. 627	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 12 4	
WAS ATTACHED TO MAIN 72 3	NAME OF CONTRACTOR Collise Le reales
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
	FAIF 5 Cues CERNIE CERNIE CONTRACTOR CONTRAC
SIGNED RECO Inspector for City	FILED AT ENGINEER'S OFFICE
Park t	

## Nº 10753

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON	і, оню,	729
RECEIVED OF	Lastreel	? . 	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	<u> </u>		
TO TOP IN SECTION	SEWER ON THE	<u></u>	J. J. San Jan J. San Jan J. San Jan Jan J. San Jan Jan Jan Jan Jan Jan Jan Jan Jan J
or June 12			
THE PREMISES BEING LOT NO	3037	, HOUSE NO	677
WORK TO BE DONE IN ACCORDANCE WI'	TH ORDINANCE NO. 19-1971		
NAME OF CONTRACTOR	<u> </u>		

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.