Nº 10766

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-26-98	IF SO HOW AND LOCATION FROM / 5 2				
HOUSE NO. 2325					
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB? 165	No.				
2.3	NAME OF CONTRACTOR Malarente				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
	10'084" 6 DEEP				
	20'				
SIGNED Bill Inspector for City	FILED AT ENGINEER'S OFFICE				
$(x_1, x_2, \dots, x_n, x_n, x_n, \dots, x_n, x_n, x_n, x_n, x_n, x_n, x_n, x_n$					

## Nº 10766

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, $Q_{c+}$ 22			
RECEIVED OF	Smitis D-4	ELURANGA E.	<i>Ca2</i> F	EE OF \$_SQ
FOR WHICH PERMISSION IS GRANTED. $\mathcal{M}_{A\leftarrow C}$	1415 EXC			·
TO TAP	SEWER ON T	HE	50 <u>077H</u>	
OF MALDONE ALE SE	AVE. ST. TYPE OF ST	REET <u>( ) : :</u>	<u> FDEWTH</u>	٠
THE PREMISES BEING LOT NO. 15년원으		, HOUSE NO	2325	nuu
WORK TO BE DONE IN ACCORDANCE WITH ORDI OF THE DEPARTMENT OF PUBLIC SERVICE.	NANCE NO. 19-19	71 DULY PASSED	BY THE CITY C	OUNCIL, AND
NAME OF CONTRACTOR WALRESTE	xcallag			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.