

Nº 10769

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11-3-98

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2305-2315

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Insert

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

fix



SIGNED B. J. Ryan
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10769

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov 2

RECEIVED OF William P. Carson FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Tenant Exc

TO TAP CANTARY SEWER ON THE SOUTH

OF 2325 P. C. DR. AVE. ST. TYPE OF STREET RESIDENTIAL (PRIVATE)

THE PREMISES BEING LOT NO. PT. 21. 768 HOUSE NO. ~~2307~~ 2305

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TISSOT Exc

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.