Nº 10770

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-16-98	FIRST MANHOLE DOWN STREAM COES TRIO WH
HOUSE NO. 2225	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	of butter
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR
SHOW BY DIAGRAM, RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	7'544 32' 5'255 NA 2450 2' 8'6" DEEP
SIGNED Bill Canala Inspector for City	FILED AT ENGINEER'S OFFICE
DEMARKS.	

Nº 1077€

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	<i>f</i> , <i>t</i>
	MASSILLON, OHIO,
RECEIVED OF	Late linely west FEE OF \$50
	and the second s
FOR WHICH PERMISSION IS GRANTED	Spelalucite Efficienting
TO TAP 10 10 10 10 10 10 10 10 10 10 10 10 10	SEWER ON THE
	AVE. TYPE OF STREET AND AND A
	17.95 HOUSE NO. 3225
•	
WORK TO BE DONE IN ACCORDANCE	WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SEI	RVICE.
NAME OF CONTRACTOR	louite

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.