N^{0} 10771

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
SIZE OF PIPE USED	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	ALL OF BUILDING SERVED.
9 2 2	the control of the co
	· ·
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for Cit	y ·
PEMARKS	

Nº 10771

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Nov 12.			
RECEIVED OF	T. Wales	BURNETT		FEE OF \$/ <u>O</u> C
FOR WHICH PERMISSION IS GRANTED. 1342	ACETI.	CK		
TO TAPSA-~~-7-14-12-4	SEWE	R ON THE	E)51	
OF COMMERCE DR SW	AVE. ST. TYPE	OF STREETA32	<i>FALT</i>	
THE PREMISES BEING LOT NO	· 	, HOUSE NO		
WORK TO BE DONE IN ACCORDANCE WITH ORE OF THE DEPARTMENT OF PUBLIC SERVICE.	DINANCE NO.	19-1971 DULY PAS	SED BY THE CITY	COUNCIL, AND
NAME OF CONTRACTOR BURKETT	Exc			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.