Nº 10774

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-17-98 HOUSE NO. 1840 1720?	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR Dans Sur			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	605F) 5'0KJ"			
SIGNED Bill Parnows	13'22° 12'12'DEE/			
SIGNED / LOS / Inspector for City	FILED AT ENGINEER'S OFFICE			

Nº 10774

OFFICE OF THE DIRECTOR OF PUBLIC SE

	, MA	ssilloņ, ohio,	
RECEIVED OF			
FOR WHICH PERMISSION IS GRANTED	<u> </u>	Lepann	Ode
/ TO TAP	• 1		7
OF Charles Aly	· *		•
THE PREMISES BEING LOT NO.			1820
WORK TO BE DONE IN ACCORDANCE W	TITH ORDINANCE NO. 19		1 1 1
OF THE DEPARTMENT OF PUBLIC SERV	# #		
NAME OF CONTRACTOR	haring the	1-11-6-19-	
Note: This permit c	overs work out	side of buildi	ng only. Any work

walls of building is subject to Massillon Board of Health Regulations.