Nº 10777

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1/- 30.98	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 23/5	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
SIZE OF PIPE USED	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	R-4 CA
	NAME OF CONTRACTOR Rondrage Egg.
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
<i>+ N</i>	6 25 p 7 7 7 26'
	10 10 10
Billenne	FILED AT ENGINEER'S OFFICE
SIGNED // Inspector for City	TIED AT ENGINEERS OF THE PARTY
REMARKS	

№ 10777

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	. · 	MASSILLON,	OHIO,	-4/20
RECEIVED OF	Sofficial	ent H	المتعمورية وأورية واسيده	FEE OF
FOR WHICH PERMISSION IS GRAN	TED			
то тар		SEWER ON THE		
OF 17 phone tue	John Stranger	AVE.	T	<u> </u>
THE PREMISES BEING LOT NO			1 and the second	1. 2. 1
THE PREMISES BEING LOT NO	7-26		_, HOUSE NO	
WORK TO BE DONE IN ACCORDA	NCE WITH ORDINA	NCE NO. 19-1971	DULY PASSED BY	THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC	SERVICE.			
	/	**************************************		
NAME OF CONTRACTOR				
Note: This pern	nit covers w	ork outside	of building	only. Any wor

walls of building is subject to Massillon Board of Health Regulations.