Nº 10784

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2 - 3 - 9 9	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 628	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 75	
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR Don Dick
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	450 - 197 197 197 197 197 197 197 197 197 197
SIGNED Bill Pommi Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 10784

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

į.	MASSILLON, OHIO,
RECEIVED OF WILLIAM	Coffee of \$57
FOR WHICH PERMISSION IS GRANTED	<u> </u>
TO TAPSE	WER ON THE
OF 30 AVE. TO ST. TO	PE OF STREET 110 NACL 4
THE PREMISES BEING LOT NO.	and the state of t
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	O. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.