N° 10795

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	<u>-</u> -	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO	NAME OF CONTRACTORWALL OF BUILDING SERVED.	
· Septimal		
SIGNED BALO Panan	FILED AT ENGINEER'S OFFICE	
PEMARKS NG IN SOF at	FILED AT ENGINEER'S OFFICE	

Nº 10795

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, OHIO,	12//5 FEE OF \$57
FOR WHICH PERMISSION IS GRANTED	<i>_</i>	
то тар	WER ON THE	vet
of 1/1 the factor of AVE. T	YPE OF STREET	exhalt
THE PREMISES BEING LOT NO. 15182		g ^g
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR LA CR	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
7-00-1	•	·

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.