

Nº 10798

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-10-99

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 331

SIZE OF PIPE USED. —


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Cotton Wrecking

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bio _____ FILED AT ENGINEER'S OFFICE

Inspector for City

REMARKS _____

Nº 10798

OFFICE OF THE DIRECTOR OF PUBLIC SE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/21

RECEIVED OF

Cottrell Wrecking

FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED

TO TAP

Cutoff Laundry

SEWER ON THE

South

OF

Lincoln Way E

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

273

, HOUSE NO.

331

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Cottrell

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.