Nº 10810

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN NAME OF CONTRACTORSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
The second secon				
SIGNEDInspecto				

Nº 10810

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO, Feb 5		
RECEIVED OF	Summit Homes		FEE OF \$50
FOR WHICH PERMISSION IS GRANTED			
TO TAP SZALTZY	•		
OF MAJONA LINIVERSIT	AVE.	Asphalt	. · · · · · · · · · · · · · · · · · · ·
THE PREMISES BEING LOT NO. 157	11	HOUSE NO. 1/144	2490
WORK TO BE DONE IN ACCORDANCE WITH			
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR CARDE	ser Excavat	1990	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.