Nº 10823

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-3-9-7	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 104			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 725	∠0		
WAS ATTACHED TO MAIN 7/2 5	NAME OF CONTRACTOR Cothure Consultation		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	J. L'DERP		
	2000		
SIGNED TO ELLE OF SE	FILED AT ENGINEER'S OFFICE		
Inspector for City			
DEMADKS .			

Nº 10823

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

/	MASSILLON, OHI	0,	/_/
RECEIVED OF			FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
10 IAP MA Sombales	sewer on the	lit	
of the fifty of A's			l
	, но		4
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN			COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR ALL LILL	· · · · · · · · · · · · · · · · · · ·		
	26		

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.

Nº 10824

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-30-9 9	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 2380			
SIZE OF PIPE USED 6 1/	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
	CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 75 E			
WAS ATTACHED TO MAIN 14 6	NAME OF CONTRACTOR Malaritie Colice.		
· .			
	LL OF BUILDING SERVED.		
signed Bill Carrier for City	FILED AT ENGINEER'S OFFICE		