Nº 10849

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-12-99	IF SO HOW AND LOCATION FROM 96 FIRST MANHOLE DOWN STREAM 96			
HOUSE NO. 14/4				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?_No				
WAS ATTACHED TO MAIN 755 5	NAME OF CONTRACTOR Burkett Gre			
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.			
	- Jagest			
	[] 2 45° AL			
	E 120'			
	→n' /45°			
	121 450			
Bill Con	FILED AT ENGINEER'S OFFICE CALL			
Inspector for City				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED. V V V V V V V V V			

Nº 10849

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	· · · · · · · · · · · · · · · · · · ·	MASSILLON, OH	lo,	
RECEIVED OF) 			FEE OF \$
FOR WHICH PERMISSION IS GRANTED	- Frank	: - [-[-		
TO TAP				<u> </u>
OF- THE MENT OF THE SECTION OF	AVE.	YPE OF STREET	<u> </u>	The state of the s
THE PREMISES BEING LOT NO.				
WORK TO BE DONE IN ACCORDANCE W OF THE DEPARTMENT OF PUBLIC SERV	ITH ORDINANCE N			
NAME OF CONTRACTOR	of the second se		-	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.