
Nº 10862

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-25.99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2720	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN 44 5	NAME OF CONTRACTOR Bontrager Exe
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	10' 4 52' 10' DEEP
media manganan dan men	22°
SIGNED Bio Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 10862

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER



Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.