## Nº 10872

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-9-99 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2575	
SIZE OF PIPE USEDDISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 7	
WAS ATTACHED TO MAIN VES NAME OF CONTRACTOR BONELINGER GE	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
7'DEEP	
(x, y)	
SIGNED BULL DOWN FILED AT ENGINEER'S OFFICE.	
SIGNEDFILED AT ENGINEER'S OFFICEFILED AT ENGINEER'S OFFICE	
REMARKS	

## Nº 10872

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

8,1997	MASSILLON, OHIO, July E
ice in home	RECEIVED OF FEE OF \$ 50
EN AVE Su.	FOR WHICH PERMISSION IS GRANTED
ol.	TO TAPSEWER ON THESEWER ON THE
-	OF
3 Z	THE PREMISES BEING LOT NO. 1565 T. HOUSE NO. 7 795
95	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
rtoager	NAME OF CONTRACTOR BUNTRAGE EXC
	Note: This permit covers work outside of building only. Any worl

walls of building is subject to Massillon Board of Health Regulations.