

Nº 10882 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-6-99

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 126

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Volpe Etc.

REPAIR
LINE 220



13'
10' 3\"/>
6' DEEP

SIGNED

B. P. [Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair Line

Nº 10882

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/16

RECEIVED OF

Walpe Excavating

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED

TO TAP

Repair Sewerage

SEWER ON THE

OF

26th St SE

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

HOUSE NO.

126

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Walpe

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**