Nº 10883

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	the state of the s			
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WA	NAME OF CONTRACTORALL OF BUILDING SERVED.			
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			
- · · · · · · · · · · · · · · · · · · ·	No Inspection			
	en e			
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE			
REMARKS	у.			

## Nº 10883

## OFFICE OF THE DIRECTOR OF PUBLIC SE

		MASSILLON, OHIO,		7/19
RECEIVED OF	-Joza	A de	pr/	FEE OF 57
FOR WHICH PERMISSION IS GRANTED	<i>U</i>			
TO TAP In na falley	SF	EWER ON THE	land	
		YPE OF STREET		alt
THE PREMISES BEING LOT NO	15714	, Hous	E NO	400
WORK TO BE DONE IN ACCORDANCE W		40. 19-1971 DULY P	ASSED BY THE C	ITY COUNCIL, AND

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.