Nº 10885

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-3.99 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
HOUSE NO/_/				
WAS LATERAL AT CURB? YES NAME OF CONTRACTOR Mulamitae Contractor				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
SIGNED BUILD FILED AT ENGINEER'S OFFICE. REMARKS No SINGL MEASUR MENTS				

Nº 10885

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLO	и, оню, 7/2	4
	Walaut		4-
RECEIVED OF	- Il place	<u> </u>	FEE OF 🞾
	r		
FOR WHICH PERMISSION IS GRANTI	ED		
TO TAP JAMES TO	SEWER ON THI	e la	<u> </u>
or Wheaton Cu			
THE PREMISES BEING LOT NO	15655	, House No/	1114
WORK TO BE DONE IN ACCORDANC	•		
OF THE DEPARTMENT OF PUBLIC S	SERVICE.		
NAME OF CONTRACTOR 121	ind her ask Do	سسرازه ا	
·	Λ	//	•
Note: This permit	t covers work outside	$^{m{arphi}}$ of building on	ly. Any work

walls of building is subject to Massillon Board of Health Regulations.