Nº 10918

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-28-99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 38-6		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	and the second of the second o	
يىر جو <u>ل</u> د	NAME OF CONTRACTOR & & EVE	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	15 24 1 12 10 REP	
	5' 10'. FY" L'DEE/	
	5'4	
Bid	FILED AT ENGINEER'S OFFICE	
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE	
DEMARKS	and the second of the second o	

Nº 10918

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

\mathcal{J}	MASSILLON, OHIO,	9/18
RECEIVED OF	Lewwood	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Ex Causting	
TO TAPSEN	WER ON THE	
OF ST. TY	PE OF STREET AND SALE	<u></u>
THE PREMISES BEING LOT NO. /1859	, HOUSE NO. 38	6
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	0. 19-1971 DULY PASSED BY THE CI	TY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR DISTANCE	<u></u>	

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.