## Nº 10927 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 10-19-99   | IF SO HOW AND LOCATION FROM 165                     |
|---|---|
| HOUSE NO. 1/27  | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT |
| WAS LATERAL AT CURB? 77 5   | CURB LINE AND DEPTH                                 |
| WAS ATTACHED TO MAIN_ 72  | NAME OF CONTRACTOR Bie Die                          |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WA   | -5' 7'DREP  |
|   | 5'-16'xy"   |
| Marin | 241 220   |
|   | 5' 8'BER 9  |
| SIGNEDInspector for City  | FILED AT ENGINEER'S OFFICE                          |
| REMARKS   |   |

## Nº 10927

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

|  | ,                                   | . / _        |
|--|-------------------------------------|--------------|
|  | MASSILLON, OHIO,                    | 0/15         |
| RECEIVED OF Charlet                            | ££                                  | FEE OF \$=50 |
| FOR WHICH PERMISSION IS GRANTED BULK           | Dick)                               |              |
| TO TAP SAMEALLY SE                             | EWER ON THE AUCRE                   |              |
| of Whatou Cu DE AVE. TO                        | YPE OF STREET ANDRO                 | C            |
| THE PREMISES BEING LOT NO                      | /                                   | 7            |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N | 40. 19-1971 DULY PASSED BY THE CITY | COUNCIL, AND |
| NAME OF CONTRACTOR CLOCK LT                    | <u></u>                             |              |
|  |                                     |              |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.