Nº 10929

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12.3-59	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. /3 44			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
WAS LATERAL AT CURB? 455	CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN 15	NAME OF CONTRACTOR Molarita Efe		
	LOG BUU DING CERVED		
SHOW BY DIAGRAM RELATION OF LATERAL TO WAR	L OF BUILDING SERVED.		
•	450 71		
	229 8		
	450 750 8 DET		
SIGNED (Inspector for City	FILED AT ENGINEER'S OFFICE		
•			

Nº 10929

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	М	ASSILLON, OHIO, 10	121	
RECEIVED OF	Mrs	Latua	FEE OF	<u>, 5</u>
FOR WHICH PERMISSION IS GRANTED	Malavite	Excounting	·	
TO TAP SUNITURY	SEWE	R ON THE COST		
of Juhaga St	AVE.	OF STREET 05ph	aH	
THE PREMISES BEING LOT NO. 538				
WORK TO BE DONE IN ACCORDANCE WITH DF THE DEPARTMENT OF PUBLIC SERVICE	ORDINANCE NO.			
NAME OF CONTRACTOR Malavil	<u>e</u>			

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.