N^{0} 10930

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-22, 99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2160	· · · · · · · · · · · · · · · · · · ·	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 725		
WAS ATTACHED TO MAIN 725	NAME OF CONTRACTOR Bain Color	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	150 30° A	
45° 13' DEE 12		
	45 750 (3 DEE)	
SIGNED Breo Sinspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 10930

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

1	MASSILLON, OHIO,
/ <u>/</u>	
RECEIVED OF	4 Callating FEE OF ST
·	
OR WHICH PERMISSION IS GRANTED	
A	100 -
O TAP SECULATION SE	WER ON THE
F Lit At the Wig S SAVE.	
HE PREMISES BEING LOT NO	اؤ
TE FREMISES DEING LOT NO	
ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	IO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
F THE DEPARTMENT OF PUBLIC SERVICE.	
Buil	
AME OF CONTRACTOR	
₹	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.