Nº 10932

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-25-99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2210		
SIZE OF PIPE USED 67	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 25	and the second of the second o	
WAS ATTACHED TO MAIN 1/2 5	NAME OF CONTRACTOR Maleutes End	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	2/	
220	-13+6×4",7 DFA	
SIGNED BORD 22°	9 DEEP AT ENGINEEDIG OFFICE	
Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 10932

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO
RECEIVED OF	AUTE EXC FEE OF \$ 1
FOR WHICH PERMISSION IS GRANTED	
TO TAP. SALTERY	SEWER ON THE SOLL TEST
OF JULIERSITY OF SE	NVE. ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 15791	, HOUSE NO. 2210
WORK TO BE DONE IN ACCORDANCE WITH ORDINAL OF THE DEPARTMENT OF PUBLIC SERVICE.	NCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR WOLLD TO THE	Hirms 14 Ashilen
Note: This permit covers w	ork outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.