## Nº 10947

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-23-99 HOUSE NO. 2255 2355 2	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 455	NAME OF CONTRACTOR Molaritas Elec		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
SHOW BY DIAGRAM RELATION OF EXTERNE TO WALL OF BUILDING SERVED.			
	170EEP		
	\frac{8}{5'} 220 \rightarrow \frac{5'}{4'}		
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE		

## Nº 10947

## OFFICE OF THE DIRECTOR OF PUBLIC SE

		11/10
	MASSILLON, OHIO,	<i></i>
RECEIVED OF	with Execut	ATIMO FEE OF \$52
OR WHICH PERMISSION IS GRANTED		<u>_</u>
TO TAP Jan Lily SE	WER ON THE	ect-
	•	
THE PREMISES BEING LOT NO. / 700	HOUSE NO	2217
YORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N		
OF THE DEPARTMENT OF PUBLIC SERVICE.	/	
NAME OF CONTRACTOR USALEMAN	<u> </u>	
. <i>[ ]</i>		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.