## Nº 10949

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-22-99 HOUSE NO. 23/0	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO.				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? 75 5				
WAS ATTACHED TO MAIN 15	NAME OF CONTRACTOR Bontsagar Exe.			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
parties of the second of the s	26' 26' 22' 12EF			
SIGNED Bill anno	7 D"			
Inspector for City				
DEMADKS				

## Nº 10949

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,		11/12
RECEIVED OF	Efficient	Homes	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Balluger Exem	valias	
то тар \$2.41.44.1	~		
OF TIGHT CITCLE SE			
THE PREMISES BEING LOT NO. 157			
WORK TO BE DONE IN ACCORDANCE WITH			
OF THE DEPARTMENT OF PUBLIC SERVICE.			:
NAME OF CONTRACTOR	f-C		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.