Nº 10960

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-30.99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. /337	
0.22 0	DISTANCE FROM FIRST MANHOLE TOOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 18 5	
WAS ATTACHED TO MAIN 15 5	NAME OF CONTRACTOR Collise Wines
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	SIDEWALL IN FRONT
	1 25' NA
SIGNED But Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 10960

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	12/3
RECEIVED OF	Athlie	FEE OF \$. /
OR WHICH PERMISSION IS GRANTED		##
TAP	SEWER ON THE	Must
OF GUARANTE	*	
THE PREMISES BEING LOT NO	-	,
YORK TO BE DONE IN ACCORDANCE WI		
OF THE DEPARTMENT OF PUBLIC SERVI	CE.	
NAME OF CONTRACTOR	4. Hill	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.