Nº 10971

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /- 6.00 HOUSE NO. 1805	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? 15.5. WAS ATTACHED TO MAIN 25.5.	NAME OF CONTRACTOR Malatic Commence			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
N	7'05EP 3' paa, 5			
SIGNED Bio Inspector for City	FILED AT ENGINEER'S OFFICE			
REMARKS				

Nº 10971

OFFICE OF THE DIRECTOR OF PUBLIC SE

			1
	/) MASSILLO	N, OHIO,	,
RECEIVED OF		1 //	
RECEIVED OF		<u> </u>	FEE OF \$≥≥≟
		\mathcal{M}	
FOR WHICH PERMISSION IS GRANTED	<i>.</i>	<u> </u>	
TO TAP	SEWER ON TH	E <u></u>	<u> </u>
of			
THE PREMISES BEING LOT NO.	*		
WORK TO BE DONE IN ACCORDANCE W	ITH ORDINANCE NO. 19-197		
OF THE DEPARTMENT OF PUBLIC SERV	ICE.	•	
NAME OF CONTRACTOR	auite		

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.