

Nº 10979

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-27-00

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM 307.5'

HOUSE NO. 350


SIZE OF PIPE USED 6"  
DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] 307.5'  
Inspector for City 8'

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10979

OFFICE OF THE DIRECTOR OF PUBLIC SE

PERMIT TO TAP SEWER

MASSILLON, OHIO, *11/25*

RECEIVED OF *Thiess*

FEE OF \$ *5.00*

FOR WHICH PERMISSION IS GRANTED

TO TAP *Shelburne*

SEWER ON THE *Post*

OF *Waller Rd. E.W.*

AVE.

ST. TYPE OF STREET *1947 Rd.*

THE PREMISES BEING LOT NO. *15, 16*

HOUSE NO. *300*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Thiess*

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**