## $N^{0}$ 10995

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-10-00	IF SO HOW AND LOCATION FROM 203 ' FIRST MANHOLE DOWN STREAM	
HOUSE NO. 360		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?YES		
WAS ATTACHED TO MAIN YCS	NAME OF CONTRACTOR	<u>-</u>
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.	
	JOU NUME	
•	9'do@house	
	20′—	
	2218,	
	-10'	
	11. dbErg # 1. 31.	
, ,	203' B'stock@nain, 31	
a the salling	8*	
SIGNED My Inspector for City	FILED AT ENGINEER'S OFFICE	

## Nº 10995

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

·	MASSILLON, OHIO,	02/09-
RECEIVED OF		FEE CF \$
FOR WHICH PERMISSION IS GRANTED	The Thomas	<del>}</del>
TO TAP	SEWER ON THE	
TO TAP	AVE. ST. TYPE OF STREET	<u> </u>
THE PREMISES BEING LOT NO	, House	NO
WORK TO BE DONE IN ACCORDANCE WITH ORDIN OF THE DEPARTMENT OF PUBLIC SERVICE.	NANCE NO. 19-1971 DULY PA	SSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR		<b></b>

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.