## 10997

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2.12.00	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2399		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 42 5	;	
WAS ATTACHED TO MAIN 12 5	NAME OF CONTRACTOR Jan Garage	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	12 12 22° 12 2° 12° 12° 12° 12° 12° 12°	
SIGNED Bild award		
SIGNED 73.40 Canada Inspector for City	FILED AT ENGINEER'S OFFICE	
·		
REMARKS		

## Nº 10997

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	2/18
RECEIVED OF		FEE OF \$
FOR WHICH PERMISSION IS GRANTED.		
TO TAP	SEWER ON THE	<u> </u>
- 1 had - 1 1.	AVE.	The second second
THE PREMISES BEING LOT NO.	, House	NO. 2399
WORK TO BE DONE IN ACCORDANCE W	ATH ORDINANCE NO. 19-1971 DULY PA	SSED BY THE CITY COUNCIL, AND
		4
NAME OF CONTRACTOR	A second	

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.