Nº 11000

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3-00	IF SO HOW AND LOCATION FROM Toes INTO WH
HOUSE NO. 3265	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO.	·
WAS ATTACHED TO MAIN 75 5	NAME OF CONTRACTOR TO alsower Geo. O Mt Ruby AUE
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
114	O Mit Ruby 1786
SIGNED Bio Signed	FILED AT ENGINEER'S OFFICE
Inspector/for City	•
REMARKS No Measur	ments.

Nº 11000

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OH	10,	2/2/
RECEIVED OF	Don't Auch	ساريلوس	FEE OF \$ <u>1</u>
OR WHICH PERMISSION IS GRANTED			
O TAP			
F 1/ 1/1 - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	AVE.	<u>Aurila</u>	1-1-
HE PREMISES BEING LOT NO			
ORK TO BE DONE IN ACCORDANCE WITH OF	RDINANCE NO. 19-1971 DULY	Y PASSED BY THE CI	TY COUNCIL, AND
IAME OF CONTRACTOR	3112/4		

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.