Nº 11011

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-2-00 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 4/5			
SIZE OF PIPE USED			
WAS LATERAL AT CURB? 46.5			
WAS ATTACHED TO MAIN 725 NAME OF CONTRACTOR HEW CONS			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
121 5' DEED DEED D			
SIGNED Bill Barrier FILED AT ENGINEER'S OFFICE			
inspector for City			
REMARKS			

Nº 11011

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, O	но,
RECEIVED OF		
FOR WHICH FERMISSION IS GRANTED	/ <u>/</u>	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
ТО ТАР		14 12 1 A-1
OF		
THE PREMISES BEING LOT NO.		
WORK TO BE DONE IN ACCORDANCE WITH ORD OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	<u> </u>	

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.