Nº 11012

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-17-00	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2260		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	er ist
WAS LATERAL AT CURB? 5		
WAS ATTACHED TO MAIN 75	NAME OF CONTRACTOR JACK	li Ep.
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL		/
4:	15° 40° 71066/2	To the state of th
SIGNED Bill Inspector for City	FILED AT ENGIN	EER'S OFFICE
REMARKS		·

Nº 11012

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	// MASSILLON, OH	l io,	3/6
RECEIVED OF	Lumet	Horney	✓ FEE OF \$5 €
FOR WHICH PERMISSION IS GRANTED	Laplada	<u>u) </u>	
TO TAP SANITALLY	/ sewer on the	lad	
of Muchaty Dr JE	AVE. ST. TYPE OF STREET	aspla	ut
THE PREMISES BEING LOT NO. 117	§ 9, H	ر کیرےOUSE NO.	260
WORK TO BE DONE IN ACCORDANCE WITH ORE OF THE DEPARTMENT OF PUBLIC SERVICE.	DINANCE NO. 19-1971 DUL	Y PASSED BY THE (CITY COUNCIL, AND
NAME OF CONTRACTOR JUANA	it Honel		÷

Note: This permit covers work outside of building only. Any worl

walls of building is subject to Massillon Board of Health Regulations.