Nº 11033

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-29.00	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 420	DISTANCE FROM FIRST MANHOLE			
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? 725	CORB LINE AND DEI III			
WAS ATTACHED TO MAIN 7	NAME OF CONTRACTOR 76 6 Cons			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	The state of the s			
	1095			
	3/-52 11/5			
•	3055			
	24'			
	9 DEEP			
SIGNED But asses	FILED AT ENGINEER'S OFFICE			
Inspector for City				
DEMARKS.				

№ 11033

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	/ MASSILLON, OH		3/28
RECEIVED OF	\rightarrow /		FEE OF \$5
OR WHICH PERMISSION IS GRANTED			
O TAP	SEWER ON THE	last	·
orap January	AVE. ST. TYPE OF STREET	and l	alt_
HE PREMISES BEING LOT NO.	<u> 1111, ,</u> ,	OUSE NO.	
YORK TO BE DONE IN ACCORDANCE WITH OF			
F THE DEPARTMENT OF PUBLIC SERVICE.	\cap		
NAME OF CONTRACTOR	Duc		

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.