Nº 11035

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

4/5/00	IF SO HOW AND LOCATION FROM 116'
HOUSE NO. 2945	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
yes was lateral at curb?	CURB LINE AND DEPTH
yes was attached to main	NAME OF CONTRACTOR_HOLDERDOUM
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED. 2945 Stanton 1.5'dp 5' o-c/p 5' 0-c/p 7' 45°
	45° ½ 27′ – 52°
a Mar un Mus	e 116'
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 11035

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	The Mark the Work	MASSILLON, OHIO, March 29
	RECEIVED OF	FEE OF \$
	FOR WHICH PERMISSION IS GRANTED	baum's
Karanta Ca	TO TAP SANTARY SEW	ER ON THE SOUTH
	OF STATED AVE. NIN AVE. TYPE	
	THE PREMISES BEING LOT NO. 3777 15135	5, HOUSE NO. 2945
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
ed a seg	NAME OF CONTRACTOR FORESTEE	

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.