Nº 11037

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3/31/00	IF SO HOW AND LOCATION FROM 129'					
325	FIRST MANHOLE DOWN STREAM					
House No6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT					
yes was Lateral at curb?	CURB LINE AND DEPTH					
yes	NAME OF CONTRACTOR					
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LL OF BUILDING SERVED.					
	325 Noble					
	129'					
SIGNED Della in they	8'					
Inspector for City						
REMARKS						

Nº 11037

and the second of the second o

and the property of the

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

				¹⁰ 17. ⋅ MA	SSILLON, OHIC) <u>, </u>	March_	30
	RECEIVED OF.					e 177 e		FEE OF \$
FOR	WHICH PERMISS	ION IS GRANTE	:D.:	Ticso	Erwo	4119		<u>-</u>
то т	TAP5/	arilory		LLÀ LISEWER	ON THE		est	· · · · · · · · · · · · · · · · · · ·
OF_	Mobile	Place	/NLJ	AVE. ST. TYPE (OF STREET	<u> </u>	sehat.	
THE	PREMISES BEING	G LOT NO	151	1920	, нос	JSE NO	325	
	RK TO BE DONE I THE DEPARTMENT			RDINANCE NO. 1	9-1971 DULY	PASSED B	Y THE CITY	COUNCIL, AND
	45 OF GONTDAGT	· -	-A					

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.